

## 916 Ti-Touch Firmware Version 5.916.0040

Release Notes 8.916.8008EN

CH-9100 Herisau
Switzerland
Phone +41 71 353 85 85
Fax +41 71 353 89 01
info@metrohm.com
www.metrohm.com

Release Notes EN

#### 1 Purpose

This document describes new features, improvements as well as fixed bugs and problems in the following new firmware version:

**5.916.0040** 

in comparison with the previous version.

**5.916.0033** 

#### 2 New features

- A new version of the 916 Ti-Touch is available, which is equipped with a built-in magnetic stirrer (article number: 1.916.0020).
- 916 Ti-Touch now complies with FDA 21 CFR Part 11.
- 916 Ti-Touch can now perform STAT titration.
- 916 Ti-Touch supports the new 810 Sample Processor.
- Added buffer pH 1.679 by "Radiometer Analytical".
- The document 8.840.4523 Titrando Compliance Guide 840/PC Control 4.1 has been updated for the 900 Touch Control and now includes 915 KF Ti-Touch, 916 Ti-Touch, and 917 Coulometer. New article number: 8.900.4007 Compliance Guide Touch Control.

## 3 Improvements

The following buffer series have been updated: NIST (all), Fluka (all series), Merck CertiPUR 20/Titrisol (pH 12.000), Merck CertiPUR (25 °C) (pH 4.00 and pH 10.00).

# 4 Fixed Bugs and Problems

- If in the dialog **Dosing unit / PREP parameters** the volume was set to **cylinder volume** , the PREP run did not work correctly.
- If a determination was canceled in the dialog **Electronic signature** , the determination did not end correctly.

\_\_\_\_\_

- If a report was manually created out of a determination by means of Print ➤ Report ➤ Report seq. as def. in method, under certain conditions the two chapters "Results" and "Messages" were printed on top of each other.
- When in a system a balance and a USB thermal printer Neo's were used, communication problems could occur.
- An attempt to load a Metrohm subsequence template in a language which does not support Metrohm method templates, lead to hidden Metrohm method templates upon returning to the dialog Load method / New Method .
- In case there were two users with administrator rights in user administration. When one of them was set into inactive state, he could not be reset to active state.
- In the command EVAL RATE two fields were named incorrectly:
   Lower limit x and Lower limit (x + 1)
- If a report was generated manually and if the report settings were modified, each modification was tracked in the Audit Trail and the method was marked as modified.
- The text of the error message "026-111 Audit Trail" was corrected.
- The commands STAT and MAT were not displayed in the method report "Titration and measuring parameters".
- When modifying a level 1 signed method, those level 1 signatures were not completely deleted.
- The Audit Trail Viewer displayed times from the Audit Trail incorrectly.
   This problem was solved with a new version of the Audit Trail Viewer (Version 1.2).
- When executing a backup, the message 020-903 "Saving ..." was not always displayed.
- With 915 KF Ti-Touch and 916 Ti-Touch, the firmware of the sample processors (810 Sample Processor, 814 USB Sample Processor and 815 USB Sample Processor XL) could not be updated.
- In the Diagnosis area, the Remote Box test did not work correctly at MSB4.
- In the Diagnosis area, the live view did not work correctly with the beaker test of sample processors.

## **5** Compliance

The current firmware version of the 916 Ti-Touch complies with 21 CFR Part 11 and GAMP.

#### 6 Manufacturer

Metrohm AG, Ionenstrasse, CH-9100 Herisau/Switzerland

Manufacturer

Metrohm AG holds the SQS certificate ISO 9001 – Quality management system for the development, production and sale of instruments and accessories for analyses.

Herisau, May 23rd, 2017

P. Hunziker

Vice President, Head of Development M. Saba

Dr. ll. Loka

Head of Quality Management