

## 1 Purpose

This document describes the fixed bugs for the new firmware version TTM859\_v6.

## 2 Fixed bugs and problems

- The operating systems of some computers crashed, as soon as the 859 Titrotherm was connected.
- Some Thermoprobes were not recognized (error message *011-114 Read error*).
- The measuring input of the 859 Titrotherm was not always correctly recognized by **tiamo™** (error message *009-149 Device error*).

## 3 Compliance

The current software version does not contain any modifications that affect conformity of **tiamo™** regarding 21 CFR Part 11 and GAMP.

**Herisau, November 25, 2011**



Dr. J. Kleimann  
Vice President, Head of R&D



U. Kürsteiner  
Head of Quality Management