

940 IC Geräte

Metrohm AG CH-9100 Herisau Switzerland Phone +41 71 353 85 85 Fax +41 71 353 89 01 info@metrohm.com www.metrohm.com

Release Notes

1 Instruments

The firmware version below can be used with the following instruments:

- 930 Compact IC Flex
- 940 Professional IC

2 Purpose

This document describes the new features, the improvements as well as the fixed bugs and problems in the following new firmware versions:

5.940.0101

In comparison with the firmware versions:

5.940.0100

3 New features

Topic	Description
none	none

4 Improvements

Topic	Description
none	none

5 Fixed bugs and problems

Торіс	Description
System stopped	In certain cases, the IC system was stopped by mistake due to the error situation "Minimum pressure fallen below", even though the system pressure remained stable.

8.940.8029EN **1**

6 Known bugs

Topic	Description
none	none

7 Conformity

The firmware version 5.940.0101 does not contain any modifications that affect conformity of the instruments mentioned above regarding 21 CFR Part 11 and GAMP.

Herisau, June 22, 2018

P. Hunziker

Vice President, Head of Development M. Saba

Dr. U. Loka

Head of Quality Management & Regulatory Affairs

2 8.940.8029EN